zCOVER®

Innovative Accessory Provider

Installation & Maintenance Instructions for ZDUPSRK3 / ZDUPSRK5 zAdapter® Unified Power Dock Rack

What are Included:

	ZDUPSRK3	ZDUPSRK5
Unified Power Dock Rack	1	1
Global AC Adapter	1	1
Machine screws	6	10
Instruction sheet	1	1

Please read the instructions thoroughly before installation.

x1

x1

x10

x1

ZDUPSRK5

x1

x1

x6

x1

ZDUPSRK3

Figure 1. What are Included:

INSTALLATION GUIDE
ZDUPSRK3 / ZDUPSRK5 zAdapter® Unified Power Dock Rack

The ZDUPSRK3 / ZDUPSRK5 zAdapter® Unified Power Dock Rack is the accessory that you can mount multiple UDA/UDB Unified Desktop Chargers on it and make a gang charger . Screw holes have been pre-threaded on the bottom of zCover Unified Desktop Chargers and Unified Power Dock Rack to accept machine screws ONLY (Screws are included in the kit).

Figure 2. Threaded screw holes on the bottom

Step 1:
Remove Port Protector from Desktop Charger

Each Desktop Charger has a black rubber Protector on the bottom. Remove it before you process the next step

Figure 3. Remove Port Blocker from Desktop Charger

Step 2:

Fasten Desktop Charger to the Unified Power Dock Rack

Fasten all Desktop Chargers to the Unified Power Dock Rack with #1 Phillips screwdriver and 6 or 10 machine screws provided (Figure 3). Tighten the screws to a torque of 0.4 N • m (3.6 lb • in).

Make sure all Desktop Chargers sit in the slots perfectly before fasten the screws.

Figure 4. Fasten Desktop Chargers to the Unified Power Dock Rack

Step 3:

Connect AC Adapter

Connect zCover Global AC Adapter to the Unified Power Dock Rack.

Figure 5. Connect AC Adapter